

FIG.1
PRIOR ART




FIG.2
PRIOR ART




FIG.3




FIG.4




FIG.5





FIG.6



09987389 111401
"0477" 53E28660

FIG.7




FIG.8




FIG.9




FIG.10






FIG.11



11/18

FIG.12

ASTIGMATISM



090739 1101
1044 63660

FIG.13




FIG.14




FIG.15




FIG.16





FIG.17

ASTIGMATISM



09987389-1140
TOTT " 68E/8650

FIG.18





FIG.19

ASTIGMATISM



09937389 111401